



1409(1409V)

1	1401008	1	Drill Chuck				
2	2004089	1	Spindle (1409)				
	2004079-1	1	Spindle (1409V)				
3	0604011	1	Ball Bearing 6201-VV				
4	2203120	1	Retaining Ring C-12				
5	1905087	1	Helical Gear				
6	2102030	1	Spindle Bushing				
7/18	1607065S	1	Motor Housing Set (R+L)				
8	3301004	6	Hex. Nut M4				
9	0604002	1	Ball Bearing N626-2RS				
10	0903023	2	Carbon Brush Holder				
11	0901023	2	Carbon Brush				
12	1803055	1	Armature Assembly (1409 115V)				
	1803052	1	Armature Assembly (1409V 115V)				
	1804055	1	Armature Assembly (1409 230V)				
	1804052	1	Armature Assembly (1409V 230V)				
13	0604002	1	Ball Bearing N626-2RS				
14	1001066	1	Field Assembly (1409 115V)				
	1001082	1	Field Assembly (1409V 115V)				
	1002066	1	Field Assembly (1409 230V)				
	1002082	1	Field Assembly (1409V 230V)				
15	2222040	6	Spring Washer 4				
16	1209044	6	Flat Washer 4 x 7				
17	2412020	6	Pan Hd. Screw M4x20				
18							
19	0704071-1	1	Switch (1409)				
	0704051-1	1	Switch (1409V 115V)				
	0704051-2	1	Switch (1409V 230V)				
20	1604018	1	Strain Relief				
21	2492014	2	Tapping Screw TS4 x14				
22	1604234	1	Cord Guard (115/230V)				
23	1118012	1	Power Supply Cord With Plug (115/230V)				
	1103002	1	Power Supply Cord With Plug (VDE)				
	1103012	1	Power Supply Cord With Plug (SAA)				
24	1604162	1	Ferrule				
25	1402005	1	Chuck Key				
26	2201001	1	Woodruff Key 2.5 x 8				
27	2106274-1	1	Chuck Set Screw M5x83(L)				
	2905123	1	Instruction Manua l(not shown)				